

SAFETY CERTIFICATE

Office of the Dy. Chief Engineer (Con)
S.E.RAILWAY, Jharsuguda
Dated: 03/05/2021

No. DCE/CON/JSG/Kendriya Vidyalaya./Safety Certificate/

To,
The Principal,
Kendriya Vidyalaya
Jharsuguda

SUB :- Inspection Reports and Safety Certificate for one year for Kendriya Vidyalaya School

Building Jharsuguda.


Respected Sir,

With reference to above subject, joint inspection has been made at Kendriya Vidyalaya School Building, Jharsuguda on date and the following inspection reports are submitted herewith for your kind information please.

- 1- 4 Nos perplex sheet is damaged and all sheets has been getting deteriorated by weathering effect in both courtyard portico.
- 2- Roof ceiling of boy's toilet at ground floor in left wing is getting to damage, due to seepage.
- 3- Floor tiles of boys toilet at first floor is damage at same location due which seepage is coming.
- 4- North west corner toilet wall is found damped and plaster got damaged at same location.
- 5-At North west side of the building cornice plaster has been damaged which required re-plastering.

It may declare that as a whole the Building is ultimately safe at present and needs to be attended the repairing works mentioned above and may please be undertaken at an earliest.


03/05/2021
AXEN/CON/JSG


3/5/2021
SSE (Works)/JSG